

Tabbs Bay


Station: 17927

Segment: 2426

Parameter: pH

Assessment Unit: 2426C_01

2010 Water Quality Standard: 6.5 – 9.0 Standard Units



Trends are considered significant if the p-value is < 0.10

Trend is significant at $p = 0.3392$ R-Square = 0.0113 T-Value = -0.9610 Number of samples: 83

The blue regression line applies to the plot of actual values ; regression statistics are derived from regression of log-transformed data

Red lines indicate the 2010 Water Quality Standard